




This unit is manufactured to replace the OEM model and/or part number listed below in form, fit, and function.

Equivalent OEM: Collins

Equivalent MN:

Equivalent PN:

Manual Figure:

Units Tested:

DLC-800 Data Link Control Unit

Description of Operation:

The ASI-DLC-800 Maintenance Kit includes all specialized test fixtures, cables, and extender cards required to function test and repair the Collins DLC-800 Data Link Control Unit. The ASI-1934-DLC Backlight Test Fixture is available as an option.

Equipment Supplied:

ASI MN	Equivalent PN	Description
ASI-0465-DLC	827-0465-003	Test Panel, with cable
ASI-8260-DLC	646-8260-001	Extender Card, A3
ASI-8261-DLC	646-8260-002	Extender Card, A4, A5, or A6
ASI-8262-DLC	NPN	Extender Cable, A8
ASI-8263-DLC	NPN	Extender Cable, A9 (2 each)
ASI-8264-DLC	NPN	Extender Cable, A2A1
ASI-8265-DLC	NPN	Extender Cable, LCD
ASI-8266-DLC	NPN	Extender Cable, A5 or A6
ASI-0182-DLC	827-0182-001	Power Supply Test Fixture, with Pulser
ASI-8267-DLC	Fig. 907	Card Puller
ASI-8268-DLC	NPN	Dumb Terminal, HT/100E-32K

Optional Equipment:

ASI MN	Equivalent PN	Description
ASI-1934-DLC	647-1934-000	DLC Backlight Test Fixture

Note: MS-DOS computer and general purpose test equipment are user supplied.

REV 1
1-31-94